


	INTAKE	EXHAUST
ADVERTISED DURATION	286°	276°
ACTUAL CAM LIFT (in)	.370"	.360"
ROCKER ARM RATIO	1.7:1	1.7:1
CENTERLINE	112°	120°
LOBE SEPERATION	116°	
DURATION AT 0.050" CAM	244°	238°
ACTUAL VALVE LIFT (in)	.629"	.612"
VALVE CLEARANCE	.000" HYD ROLLER	.000" HYD ROLLER
RECOMMENDED SPRING KIT	BC0470	

CAMSHAFT TIMING AT 0.050" VALVE LIFT

	OPEN	CLOSES
INTAKE	7° BTDC	51° ABDC
EXHAUST	62° BBDC	2° ATDC



NOTES

- Fits LS1, LS2, LS3, LS9, LQ4, LQ9 engine makes
- Requires BC0470 spring/retainer kit due to cylinder pressure.

BC does not recommend using synthetic oil during break-in or operation. Follow OEM manufacturer's torque sequence and specifications. Use liberal amount of aftermarket engine assembly lube during installation. Check follower or bucket surfaces for abnormal wear and/or scuffing. On initial start-up and break-in run engine at 1500-2500 rpm for 20 minutes. **Camshafts damaged by improper installation, excessive spring pressure or retainers contacting valve guides or seals are void from warranty. Not legal for sale or use on emission controlled motor vehicles.**

